

Figure 1a




Figure 1b

3/8




Figure 2

Plant: ExpAspect

Support Information Support Request History Available Experts Collaboration Config

Case ID: 84

System Name: Wisetec

Object Name: BV112Sample

Object GUID: {69E92E4-2-4D8-DB26244705a}

Object Type: Block Valve Sample

System Time: 30/10/2003 14:01:18

User Name: Stationary Operator

Company Name: ABB

User Input:

Picture/Video

Take picture Take video

Service Level

Choose Criticality: Operation Critical

Send to ABB support

Maintenance History:

07/03/2001: BV112 Sample installed
 10/03/2001: Installation tests complete. Block Valve working correctly
 03/07/2002: Preventative maintenance performed

31

35

36a

36b

36c

Figure 3

30

Figure 4





Figure 5



40

Figure 6




Figure 7